

# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 1



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA766X Page Number : A1 of A3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01


Report No. : FC683103

Report Template No.: BU5-FC15B Version 1.3


# <Radiated Emission>

## Mode 3

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA766X Page Number : A2 of A3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No. : FC683103

Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA766X Page Number : A3 of A3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3

Report No. : FC683103