

Report No. : FA430801

Appendix D. Test Setup Photos





Right Cheek








Left Cheek

Left Tilted

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA405TVX Page Number : D1 of D2
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01







Front of the DUT with Phantom 1.5 cm Gap

Back of the DUT with Phantom 1.5 cm Gap

Report No. : FA430801

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA405TVX Page Number : D2 of D2 Report Issued Date : Mar. 20, 2014

Report Version : Rev. 01