

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 4



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBM340MT

: A1 of A3 Page Number Report Issued Date: Feb. 15, 2017 Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No.: FC683103-01

C Test Report Report No.: FC683103-01


Mode 3

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBM340MT Page Number : A2 of A3
Report Issued Date : Feb. 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No. : FC683103-01

Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBM340MT Page Number : A3 of A3
Report Issued Date : Feb. 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3