## 3. Internal Photograph of EUT


Brand Name: Avvio / Model Name: Avvio 560S

Report No.: EP222801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : 16 of 31
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01

Report No.: EP222801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : 17 of 31
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01



Report No.: EP222801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S

Page Number : 18 of 31 Report Issued Date : Mar. 23, 2012 Report Version : Rev. 01



Report No.: EP222801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S

Page Number : 19 of 31 Report Issued Date : Mar. 23, 2012 Report Version : Rev. 01



Report No.: EP222801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S

Page Number : 20 of 31 Report Issued Date : Mar. 23, 2012 Report Version : Rev. 01



Report No.: EP222801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S

Page Number : 21 of 31 Report Issued Date : Mar. 23, 2012 Report Version : Rev. 01



Report No.: EP222801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S

Page Number : 22 of 31 Report Issued Date : Mar. 23, 2012 Report Version : Rev. 01



Report No.: EP222801




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S

Page Number : 23 of 31 Report Issued Date : Mar. 23, 2012 Report Version : Rev. 01


Report No.: EP222801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : 24 of 31
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01



Report No.: EP222801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S

Page Number : 25 of 31 Report Issued Date : Mar. 23, 2012 Report Version : Rev. 01


Report No.: EP222801



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : 26 of 31
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01

Report No.: EP222801



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : 27 of 31
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01


Report No.: EP222801



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : 28 of 31
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01


Report No.: EP222801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : 29 of 31
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01


Report No.: EP222801

Brand Name: Avvio / Model Name: Avvio 560S



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : 30 of 31
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01

Report No.: EP222801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : 31 of 31
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01