

Report No.: FG251703


Appendix B. Setup Photographs

<Radiated Emission>

E1-Plane

LF





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA831

Page Number : B1 of B2 Report Issued Date: Aug. 02, 2012

Report Version : Rev. 01






E2-Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA831 Page Number : B2 of B2
Report Issued Date : Aug. 02, 2012
Report Version : Rev. 01

Report No.: FG251703