3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 510 / Avvio 520


Report No.: EP410702



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 14 of 24
Report Issued Date : Jan. 23, 2014
Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 15 of 24
Report Issued Date : Jan. 23, 2014
Report Version : Rev. 01



Report No.: EP410702




TEL: 86-755-3320-2398 FCC ID: WVBA510X

Page Number : 16 of 24 Report Issued Date : Jan. 23, 2014 Report Version : Rev. 01



Report No.: EP410702




TEL: 86-755-3320-2398 FCC ID: WVBA510X

Page Number : 17 of 24 Report Issued Date : Jan. 23, 2014 Report Version : Rev. 01




Report No.: EP410702



TEL: 86-755-3320-2398 FCC ID: WVBA510X

Page Number : 18 of 24 Report Issued Date : Jan. 23, 2014 Report Version : Rev. 01

Report No.: EP410702




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA510X Page Number : 19 of 24
Report Issued Date : Jan. 23, 2014
Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 510 / Avvio 520


Report No.: EP410702



TEL: 86-755-3320-2398 FCC ID: WVBA510X

: 20 of 24 Page Number Report Issued Date : Jan. 23, 2014 Report Version : Rev. 01


Report No.: EP410702



TEL: 86-755- 3320-2398 FCC ID: WVBA510X


Page Number : 21 of 24
Report Issued Date : Jan. 23, 2014
Report Version : Rev. 01

Report No.: EP410702



TEL: 86-755- 3320-2398 FCC ID: WVBA510X Page Number : 22 of 24
Report Issued Date : Jan. 23, 2014
Report Version : Rev. 01


Report No.: EP410702



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 23 of 24
Report Issued Date : Jan. 23, 2014
Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: WVBA510X

Page Number : 24 of 24 Report Issued Date : Jan. 23, 2014 Report Version : Rev. 01

Report No.: EP410702