

## Report No. : FA381601

## Appendix D. Test Setup Photos





**Right Cheek** 







SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767 FCC ID: WVBA775X Page Number : D1 of D2
Report Issued Date : Sep. 17, 2013


Report Version : Rev. 01








Front of the DUT with Phantom 1 cm Gap



Report No. : FA381601

Back of the DUT with Phantom 1 cm Gap




Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767 FCC ID: WVBA775X

Page Number : D2 of D2 Report Issued Date: Sep. 17, 2013 : Rev. 01 Report Version