

Report No. : FA281601

Appendix D. Product Photos





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : D1 of D1
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01



Report No. : FA281601

Appendix E. **Test Setup Photos**





Right Cheek







Left Cheek



Left Tilted



Front of the DUT with Phantom 1.5 cm Gap



Back of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402

Page Number : E1 of E1 Report Issued Date: Sep. 20, 2012 Report Version : Rev. 01