3. Internal Photograph of EUT


Brand Name: Avvio / Model Name: Avvio 710

Report No.: EP231611




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 19 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Brand Name: Avvio / Model Name: Avvio 710



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 20 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 21 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Report No.: EP231611



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 22 of 35 Report Issued Date : Apr. 27, 2012

Report Version : Rev. 01





Report No.: EP231611



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710


Page Number : 23 of 35 Report Issued Date : Apr. 27, 2012 Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 24 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Brand Name: Avvio / Model Name: Avvio 710





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 25 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Brand Name: Avvio / Model Name: Avvio 710



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 26 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 27 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 28 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 29 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Report No.: EP231611



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 30 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Report No.: EP231611



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 31 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Report No.: EP231611



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 32 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Brand Name: Avvio / Model Name: Avvio 710



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 33 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Report No.: EP231611



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 34 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Brand Name: Avvio / Model Name: Avvio 710



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : 35 of 35
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01