

Report No.: FD132510-01

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1~3



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS


: B1 of B3 Page Number Report Issued Date: Jul. 05, 2011 Report Version : Rev. 01




Report No.: FD132510-01

<Radiated Emission>

Mode 1~3





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : B2 of B3
Report Issued Date : Jul. 05, 2011
Report Version : Rev. 01





Mode 4





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : B3 of B3
Report Issued Date : Jul. 05, 2011
Report Version : Rev. 01

Report No.: FD132510-01