## 1. External Photograph of EUT

Brand Name: Avvio / Model Name: H268

Report No.: EP172702



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 1 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01

Report No.: EP172702



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 2 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01

Report No.: EP172702



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 3 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01



Report No.: EP172702



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268

Page Number : 4 of 29 Report Issued Date : Nov. 09, 2011 Report Version : Rev. 01



Report No.: EP172702



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268

: 5 of 29 Page Number Report Issued Date : Nov. 09, 2011 Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 6 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01

## 2. Photograph of Accessory

Brand Name: Avvio / Model Name: H268

Report No.: EP172702

## **List of Accessory:**

Specification of Accessory		
IAC: Adanter	Brand Name	Avvio
	Model Name	DSA-3RNA-05 FUS 050065
Battery	Brand Name	Avvio
	Model Name	H268
Earphone	Туре	162cm non-shielded without core
USB Cable	Туре	100cm shielded with four cores

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 7 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01



Report No.: EP172702



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268

Page Number : 8 of 29 Report Issued Date : Nov. 09, 2011 Report Version : Rev. 01

Report No.: EP172702



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 9 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01



Report No.: EP172702



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 10 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01



Report No.: EP172702




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268

Page Number : 11 of 29 Report Issued Date : Nov. 09, 2011 Report Version : Rev. 01



Report No.: EP172702




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268

Page Number : 12 of 29 Report Issued Date : Nov. 09, 2011 Report Version : Rev. 01



Report No.: EP172702



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 13 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 14 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 15 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 16 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAH268 Page Number : 17 of 29
Report Issued Date : Nov. 09, 2011
Report Version : Rev. 01