

Report No.: FR5O1601A

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : B1 of B2
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01




Report No.: FR5O1601A


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : B2 of B2
Report Issued Date : Nov. 05, 2015
Report Version : Rev. 01