

Report No.: FA411502


## Appendix D. SAR Test Setup Photos





**Right Cheek** 

**Right Tilted** 






Left Cheek

**Left Tilted** 





Front of the DUT with Phantom 1 cm

Back of the DUT with Phantom 1 cm

SPORTON INTERNATIONAL (XI'AN) INC.


TEL: +86-029-8860-8767 FAX: +86-029-8860-8791 FCC ID: WVBA778X

Page Number : D1 of D2 Report Issued Date: Feb. 12, 2014

Report Version : Rev. 01







Right Side of the DUT with Phantom 1 cm



**Report No. : FA411502** 

Left Side of the DUT with Phantom 1 cm



Top Side of the DUT with Phantom 1 cm



Bottom Side of the DUT with Phantom 1 cm



Back, Test Separation 1 cm (with / Headset)

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: +86-029-8860-8767 FAX: +86-029-8860-8791 FCC ID: WVBA778X

Page Number : D2 of D2 Report Issued Date: Feb. 12, 2014 Report Version : Rev. 01