

# Appendix B. Setup Photographs

## <Conducted Emission>

#### Mode 3



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA821X

Page Number : B1 of B3
Report Issued Date : May 06, 2013
Report Version : Rev. 01

Report No.: FC313005







## <Radiated Emission>

### Mode 2

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA821X Page Number : B2 of B3
Report Issued Date : May 06, 2013
Report Version : Rev. 01


Report No.: FC313005





Mode 4

LF



HF



TEL: 86-755- 3320-2398 FCC ID: WVBA821X Page Number : B3 of B3
Report Issued Date : May 06, 2013
Report Version : Rev. 01

Report No.: FC313005