## 3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 295S/Avvio 295; Marketing Name: Avvio 295S/Avvio 295

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 13 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 14 of 41 Report Issued Date : Mar. 05, 2014

Report Version : Rev. 01

Report No.: EP421401




TEL: 86-755- 3320-2398 FCC ID: WVBA295X

Page Number : 15 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01


Marketing Name: Avvio 295S/Avvio 295

Report No.: EP421401



TEL: 86-755-3320-2398 FCC ID: WVBA295X Page Number : 16 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01


Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X

Page Number : 17 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01


Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X

Page Number : 18 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 19 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401


Marketing Name: Avvio 295S/Avvio 295

Marketing Name: Avvio 295S/Avvio

TEL: 86-755- 3320-2398 FCC ID: WVBA295X


Page Number : 20 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401




TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 21 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 22 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 23 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Marketing Name: Avvio 295S/Avvio 295


Report No.: EP421401



TEL: 86-755-3320-2398 FCC ID: WVBA295X

: 24 of 41 Page Number Report Issued Date : Mar. 05, 2014 Report Version : Rev. 01

Report No.: EP421401




TEL: 86-755- 3320-2398 FCC ID: WVBA295X

Page Number : 25 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Marketing Name: Avvio 295S/Avvio 295

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X

Page Number : 26 of 41
Report Issued Date : Mar. 05, 2014

Report Version : Rev. 01

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X


Page Number : 27 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 28 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 29 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401



TEL: 86-755-3320-2398 FCC ID: WVBA295X Page Number : 30 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Marketing Name: Avvio 295S/Avvio 295


Report No.: EP421401



TEL : 86-755- 3320-2398 FCC ID : WVBA295X Page Number : 31 of 41
Report Issued Date : Mar. 05, 2014

Report Version : Rev. 01


Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 32 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Brand Name: Avvio; Model Name: Avvio 295S/Avvio 295; Marketing Name: Avvio 295S/Avvio 295


Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 33 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01


Brand Name: Avvio; Model Name: Avvio 295S/Avvio 295; Marketing Name: Avvio 295S/Avvio 295

Report No.: EP421401



TEL: 86-755-3320-2398 FCC ID: WVBA295X Page Number : 34 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 35 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01


Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 36 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Marketing Name: Avvio 295S/Avvio 295

Report No.: EP421401




TEL: 86-755- 3320-2398 FCC ID: WVBA295X

Page Number : 37 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Brand Name: Avvio; Model Name: Avvio 295S/Avvio 295; Marketing Name: Avvio 295S/Avvio 295

Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X Page Number : 38 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01


Report No.: EP421401



TEL: 86-755- 3320-2398 FCC ID: WVBA295X

Page Number : 39 of 41
Report Issued Date : Mar. 05, 2014
Report Version : Rev. 01

Report No.: EP421401




TEL: 86-755-3320-2398 FCC ID: WVBA295X

: 40 of 41 Page Number Report Issued Date : Mar. 05, 2014

Report Version : Rev. 01

Report No.: EP421401



TEL: 86-755-3320-2398 FCC ID: WVBA295X

Page Number : 41 of 41 Report Issued Date : Mar. 05, 2014

Report Version : Rev. 01