

Report No. : FC311102

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Mode 3



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA29X

: B1 of B3 Page Number Report Issued Date: Feb. 06, 2013 Report Version : Rev. 01



Report No.: FC311102

<Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA29X

: B2 of B3 Page Number Report Issued Date: Feb. 06, 2013 Report Version : Rev. 01






Report No.: FC311102

Mode 3

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA29X Page Number : B3 of B3
Report Issued Date : Feb. 06, 2013
Report Version : Rev. 01