Brightstar Corporation

9725 NW 117th Ave., Miami, Florida, United States, 33178 Tel: 1 305.921-1470; Fax: 1 305.863-3367

Date: July 25, 2012

Product Equality Declaration

We, Brightstar Corporation, declare on our sole responsibility for the product of Avvio 921below:

The differences between previous and current model of Avvio 921 are as below:

- 1. Bluetooth part: resistor C501 is change from 0 ohms to 1 ohm
- 2. RF part:

Part Reference	Previous model of Avvio 921	Current model of Avvio 921
SF600	No	S)FILTER,SAW,EGSM/DCS RX,SFW942PY002,WISOL
C632	No	22pF
C640	No	6pF
C628 C629	No	2pF
L609 L611	No	18nH 4.7nH
C630 C633	No	2.7pF
C623 C627	22pF 10nH	1.0nH 5.6nH

3. SIM part: Current model of Avvio 921 have two SIM slot, while previous have only one SIM slot.

Except listings above, the others are all the same as previous version.

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely yours,

Welton Gi