

Appendix A. Setup Photographs

<Conducted Emission>

Mode 4



Mode 3



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : A1 of A3
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: FC591506


<Radiated Emission>

Mode 2

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : A2 of A3
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No. : FC591506


Report No.: FC591506

Mode 3

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : A3 of A3
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01