

Report No.: FA2N1501

## Appendix D. Product Photos






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA418S Page Number : D1 of D2
Report Issued Date : Nov. 29, 2012
Report Version : Rev. 01



Report No.: FA2N1501

## **Antenna Location:**



Antenna	Length	Width
WWAN Antenna <tx rx=""></tx>	3.6cm	3.0cm
Bluetooth Antenna <tx rx=""></tx>	1.8cm	0.1cm
EUT	10.4cm	4.4cm

The shortest distance between the Tx antennas		
WWAN Antenna <tx rx=""> to Bluetooth Antenna <tx rx=""></tx></tx>	0.1 cm	

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA418S Page Number : D2 of D2
Report Issued Date : Nov. 29, 2012

Report Version : Rev. 01




## Report No.: FA2N1501

## Appendix E. **Test Setup Photos**



**Right Cheek** 

**Right Tilted** 







**Left Tilted** 



Front of the DUT with Phantom 1.5 cm Gap (w/ headset)



Back of the DUT with Phantom 1.5 cm Gap (w/ headset)

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA418S

Page Number : E1 of E1 Report Issued Date: Nov. 29, 2012 Report Version : Rev. 01