3. Internal Photograph of EUT

Brand Name: mint / Model Name: Mint 140

Report No.: EP5O1601



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 13 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01




Report No.: EP5O1601




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 14 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01

Report No.: EP5O1601



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 15 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01


Report No.: EP5O1601



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 16 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01




Report No.: EP5O1601



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 17 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01



Report No.: EP5O1601



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 18 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01


Report No.: EP5O1601



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 19 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01




Report No.: EP5O1601




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 20 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01

Report No.: EP5O1601



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 21 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01

Report No.: EP5O1601




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 22 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01




Report No.: EP5O1601




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 23 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01

Report No.: EP5O1601




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 24 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01

Report No.: EP5O1601



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 25 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01

Report No.: EP5O1601




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 26 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01

Report No.: EP5O1601



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 27 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01

Report No.: EP5O1601



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB140M Page Number : 28 of 28
Report Issued Date : Nov. 09, 2015
Report Version : Rev. 01