
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB235M Page Number : A1 of A3
Report Issued Date : Jun. 15, 2016
Report Version : Rev. 02


Report Template No.: BU5-FC15B Version 1.1

Report No. : FC651702


<Radiated Emission>

Mode 2

LF



 ${\sf HF}$



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB235M Page Number : A2 of A3
Report Issued Date : Jun. 15, 2016
Report Version : Rev. 02

Report Template No.: BU5-FC15B Version 1.1

Report No. : FC651702


C Test Report No. : FC651702

Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB235M Page Number : A3 of A3
Report Issued Date : Jun. 15, 2016
Report Version : Rev. 02

Report Template No.: BU5-FC15B Version 1.1