

Appendix D. Product Photos





Report No.: FA313006







SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA9781 Page Number : D1 of D2
Report Issued Date : Mar. 22, 2013
Report Version : Rev. 01



Antenna Location:



Antenna	Length	Width
WWAN Antenna <tx rx=""></tx>	4.8 cm	1.8 cm
WLAN & Bluetooth Antenna <tx rx=""></tx>	2.0 cm	1.3 cm
EUT	12.0 cm	6.2 cm

The shortest distance between the Tx antennas		
WWAN Antenna to WLAN & Bluetooth Antenna	7.6 cm	


SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA9781 Page Number : D2 of D2
Report Issued Date : Mar. 22, 2013
Report Version : Rev. 01

Report No.: FA313006



Appendix E. Test Setup Photos



Report No.: FA313006

Right Cheek

Right Tilted







Left Tilted



Front of the DUT with Phantom 1 cm Gap (with / Headset)



Back of the DUT with Phantom 1 cm Gap (with / Headset)


SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA9781 Page Number : E1 of E2
Report Issued Date : Mar. 05, 2013
Report Version : Rev. 01





Front of the DUT with Phantom 1 cm Gap



Report No.: FA313006

Back of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA9781

Page Number : E2 of E2 Report Issued Date: Mar. 05, 2013 Report Version : Rev. 01