

# Appendix B. Setup Photographs

# <Conducted Emission>

### Mode 2



### Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA501X Page Number : B1 of B2
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01

Report No.: FC312402






# <Radiated Emission>

### Mode 4

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA501X Page Number : B2 of B2
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01

Report No.: FC312402