## 3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 765S/Avvio 765


Report No.: EP381603



TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 18 of 45
Report Issued Date : Sep. 13, 2013



**Report No.: EP381603** 




TEL: 86-755-3320-2398 FCC ID: WVBA765X

: 19 of 45 Page Number Report Issued Date : Sep. 13, 2013

: Rev. 02 Report Version



**Report No.: EP381603** 



TEL: 86-755-3320-2398 FCC ID: WVBA765X

Page Number : 20 of 45 Report Issued Date : Sep. 13, 2013 Report Version : Rev. 02



TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 21 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02

Report No.: EP381603



TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 22 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02


Brand Name: Avvio; Model Name: Avvio 765S/Avvio 765 80 1327 WALL RESIDENCE | 1327 40 10 400 80

TEL: 86-755-3320-2398 FCC ID: WVBA765X

: 23 of 45 Page Number Report Issued Date : Sep. 13, 2013








TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 24 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02




Brand Name: Avvio; Model Name: Avvio 765S/Avvio 765



TEL: 86-755-3320-2398 FCC ID: WVBA765X


: 25 of 45 Page Number Report Issued Date : Sep. 13, 2013 Report Version : Rev. 02

Report No.: EP381603




TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 26 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02

Report No.: EP381603




TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 27 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02

Report No.: EP381603



TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 28 of 45
Report Issued Date : Sep. 13, 2013






TEL: 86-755-3320-2398 FCC ID: WVBA765X

: 29 of 45 Page Number Report Issued Date : Sep. 13, 2013 Report Version : Rev. 02

Report No.: EP381603




TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 30 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL : 86-755-3320-2398 FCC ID : WVBA765X Page Number : 31 of 45
Report Issued Date : Sep. 13, 2013

Report No.: EP381603




TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 32 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02

Brand Name: Avvio; Model Name: Avvio 765S/Avvio 765



TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 33 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02






TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 34 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02




Report No.: EP381603




TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 35 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02

Report No.: EP381603




TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 36 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02

Report No.: EP381603



TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 37 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02

Report No.: EP381603




TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 38 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02

Report No.: EP381603




TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 39 of 45 Report Issued Date : Sep. 13, 2013

Report No.: EP381603



TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 40 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02


Report No.: EP381603




TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 41 of 45 Report Issued Date : Sep. 13, 2013

: Rev. 02

Report Version



Brand Name: Avvio; Model Name: Avvio 765S/Avvio 765




TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 42 of 45
Report Issued Date : Sep. 13, 2013

: Rev. 02


Report Version

Report No.: EP381603



TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 43 of 45 Report Issued Date : Sep. 13, 2013






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 44 of 45
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02

Report No.: EP381603





TEL: 86-755-3320-2398 FCC ID: WVBA765X Page Number : 45 of 45 Report Issued Date : Sep. 13, 2013