3. Internal Photograph of EUT

Brand Name: Avvio/UBER; Model Name: Avvio L620, Uber L620

Report No.: EP591506



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 22 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01




Report No.: EP591506



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 23 of 61 Report Issued Date : Oct. 30, 2015

Report Version : Rev. 01




Brand Name: Avvio/UBER; Model Name: Avvio L620, Uber L620

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 24 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



Report No.: EP591506




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 25 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01



Report No.: EP591506




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 26 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01



Report No.: EP591506




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 27 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01




Report No.: EP591506



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620


Page Number : 28 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01

Report No.: EP591506



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 29 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 30 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01




Brand Name: Avvio/UBER; Model Name: Avvio L620, Uber L620



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620


Page Number : 31 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620


Page Number : 32 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01

Report No.: EP591506




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 33 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591506



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 34 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01


Report No.: EP591506



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 35 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 36 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 37 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591506



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 38 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 39 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 40 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 41 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01

Report No.: EP591506



Report No.: EP591506



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 42 of 61 Report Issued Date : Oct. 30, 2015

Report Version : Rev. 01



Report No.: EP591506



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620


Page Number : 43 of 61 Report Issued Date : Oct. 30, 2015


Report Version : Rev. 01



Brand Name: Avvio/UBER; Model Name: Avvio L620, Uber L620

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 44 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 45 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



Report No.: EP591506




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 46 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01



Report No.: EP591506




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 47 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01




Brand Name: Avvio/UBER; Model Name: Avvio L620, Uber L620




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 48 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 49 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01


Report No.: EP591506



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 50 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01




Brand Name: Avvio/UBER; Model Name: Avvio L620, Uber L620




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 51 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 52 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591506




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 53 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591506




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 54 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591506




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 55 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

: 56 of 61 Page Number Report Issued Date : Oct. 30, 2015 : Rev. 01 Report Version




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 57 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591506




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 58 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 59 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



Brand Name: Avvio/UBER; Model Name: Avvio L620, Uber L620

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620 Page Number : 60 of 61
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL620

Page Number : 61 of 61 Report Issued Date : Oct. 30, 2015 Report Version : Rev. 01

Report No.: EP591506