

Report No.: FA312403

## Appendix D. Product Photos



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA516

Page Number : D1 of D2 Report Issued Date: Mar. 01, 2013 Report Version : Rev. 01



## **Antenna Location:**



Antenna	Length	Width
Bluetooth Antenna <tx rx=""></tx>	1.8cm	0.1cm
WWAN Antenna <tx rx=""></tx>	4.5cm	2.6cm
EUT	10.0cm	5.6cm

The shortest distance between the Tx antennas		
WWAN Antenna <tx rx=""> to Bluetooth Antenna <tx rx=""></tx></tx>	0.1cm	


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA516 Page Number : D2 of D2
Report Issued Date : Mar. 01, 2013
Report Version : Rev. 01

Report No.: FA312403



## Report No.: FA312403


## Appendix E. **Test Setup Photos**





**Right Cheek** 










**Left Tilted** 



Front of the DUT with Phantom 1.5 cm Gap



Back of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA516

Page Number : E1 of E1 Report Issued Date: Mar. 01, 2013 Report Version : Rev. 01