

Report No. : FA170823


Appendix D. Product Photos





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAVVIOT519 Page Number : D1 of D2
Report Issued Date : Aug. 11, 2011
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAVVIOT519 Page Number : D2 of D2
Report Issued Date : Aug. 11, 2011
Report Version : Rev. 01

Report No.: FA170823



Report No.: FA170823

Appendix E. **Test Setup Photos**



Right Cheek



Right Tilted



Left Cheek



Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAVVIOT519 Page Number : E1 of E1 Report Issued Date: Aug. 11, 2011 Report Version : Rev. 01