


Report No.: EP6N2401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ501X

Page Number : 45 of 54 Report Issued Date : Dec. 19, 2016

Report Version : Rev. 01



Report No.: EP6N2401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ501X

Page Number : 46 of 54 Report Issued Date : Dec. 19, 2016 Report Version : Rev. 01




Report No.: EP6N2401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ501X

: 47 of 54 Page Number Report Issued Date : Dec. 19, 2016 Report Version : Rev. 01


Report No.: EP6N2401



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ501X Page Number : 48 of 54
Report Issued Date : Dec. 19, 2016
Report Version : Rev. 01


Report No.: EP6N2401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ501X Page Number : 49 of 54
Report Issued Date : Dec. 19, 2016
Report Version : Rev. 01



Report No.: EP6N2401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ501X

Page Number : 50 of 54 Report Issued Date : Dec. 19, 2016


Report Version : Rev. 01

Report No.: EP6N2401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ501X Page Number : 51 of 54
Report Issued Date : Dec. 19, 2016
Report Version : Rev. 01

Report No.: EP6N2401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ501X Page Number : 52 of 54
Report Issued Date : Dec. 19, 2016
Report Version : Rev. 01

Report No.: EP6N2401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ501X Page Number : 53 of 54
Report Issued Date : Dec. 19, 2016
Report Version : Rev. 01





SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ501X Page Number : 54 of 54
Report Issued Date : Dec. 19, 2016
Report Version : Rev. 01