1. External Photograph of EUT

Brand Name: Avvio, PULSARE, WUPA

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 1 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 2 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 3 of 53 Report Issued Date : Oct. 23, 2014

Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 4 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 5 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 6 of 53
Report Issued Date : Oct. 23, 2014

Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 7 of 53
Report Issued Date : Oct. 23, 2014

Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 8 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 9 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 10 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 11 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 12 of 53
Report Issued Date : Oct. 23, 2014

Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 13 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 14 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 15 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 16 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 17 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 18 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Photograph of Accessory 2.

Brand Name: Avvio, PULSARE, WUPA

Page Number

: 19 of 53

: Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S

Specification of Accessory		
AC Adapter	Brand Name	Avvio
	Model Name	FLD0710-5.0V0.5A
AC Adapter	Brand Name	PULSARE
	Model Name	FLD0710-5.0V0.5A
AC Adapter	Brand Name	WUPA
	Model Name	FLD0710-5.0V0.5A
Battery	Brand Name	Avvio
	Model Name	4003M
Battery	Brand Name	PULSARE
	Model Name	4003M
Battery	Brand Name	WUPA
	Model Name	4003M
Earphone	Signal Line Type	119cm non-shielded without core
USB Cable	Signal Line Type	0.82m shielded without core

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (SHENZHEN) INC. TEL: 86-755-3320-2398

Report Issued Date : Oct. 23, 2014 FCC ID: WVBA777X Report Version

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 20 of 53 Report Issued Date : Oct. 23, 2014

Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 21 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 22 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Brand Name: Avvio, PULSARE, WUPA Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777S

Report No.: EP491904



TEL: 86-755-3320-2398 FCC ID: WVBA777X Page Number : 23 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 24 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 25 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 26 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 27 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01

Report No.: EP491904

Model Name: Avvio 777, Avvio 777S, Pulsare 777, Pulsare 777S, WUPA 777, WUPA 777S



TEL: 86-755- 3320-2398 FCC ID: WVBA777X

Page Number : 28 of 53
Report Issued Date : Oct. 23, 2014
Report Version : Rev. 01