## 3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 405TVS / Avvio 405TV


Report No.: EP430801




TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 12 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 13 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 14 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01




TEL: 86-755-3320-2398 FCC ID: WVBA405TVX

Page Number : 15 of 37
Report Issued Date : Mar. 20, 2014

Report Version : Rev. 01






TEL: 86-755-3320-2398 FCC ID: WVBA405TVX

Page Number : 16 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01






TEL: 86-755-3320-2398 FCC ID: WVBA405TVX

Page Number : 17 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01






TEL: 86-755-3320-2398 FCC ID: WVBA405TVX


Page Number : 18 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01

Brand Name: Avvio; Model Name: Avvio 405TVS / Avvio 405TV



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 19 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01

Report No.: EP430801



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX

Page Number : 20 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01


Report No.: EP430801



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX


Page Number : 21 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01

Report No.: EP430801



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 22 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01


Report No.: EP430801



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX

Page Number : 23 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01







TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 24 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 25 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01




TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 26 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 27 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01






TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 28 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 29 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01






TEL: 86-755-3320-2398 FCC ID: WVBA405TVX

Page Number : 30 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01






TEL: 86-755-3320-2398 FCC ID: WVBA405TVX

Page Number : 31 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01


Report No.: EP430801



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX

Page Number : 32 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01


Report No.: EP430801



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX


Page Number : 33 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01

Report No.: EP430801



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX


Page Number : 34 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 35 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01








TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 36 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : 37 of 37
Report Issued Date : Mar. 20, 2014
Report Version : Rev. 01