


Report No. : FA381604

Appendix D. Test Setup Photos





Right Cheek

Right Tilted





Left Cheek

Left Tilted

TEL: 86-029-8860-8767 FCC ID: WVBA785X Page Number : D1 of D2
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 01







Report No. : FA381604

Front of the DUT with Phantom 1 cm Gap


Back of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767 FCC ID: WVBA785X

Page Number : D2 of D2 Report Issued Date: Sep. 13, 2013 Report Version : Rev. 01