1. External Photograph of EUT

Brand Name: Avvio, PULSARE

Report No.: EP492607

Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 1 of 83 Report Issued Date : Nov. 24, 2014



Brand Name: Avvio, PULSARE Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S

Report No.: EP492607



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 2 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607

Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X

: 3 of 83 Page Number Report Issued Date : Nov. 24, 2014

Report No.: EP492607

Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X

Page Number : 4 of 83

Report Issued Date : Nov. 24, 2014

Report No.: EP492607


Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 5 of 83 Report Issued Date : Nov. 24, 2014

Report No.: EP492607

Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 6 of 83 Report Issued Date : Nov. 24, 2014

Report No.: EP492607

Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 7 of 83 Report Issued Date : Nov. 24, 2014

Report No.: EP492607



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 8 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607


Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 9 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607

Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 10 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607


Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 11 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607

Brand Name: Avvio, PULSARE Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 12 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: Avvio, PULSARE

Report No.: EP492607

Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S

Specification of Accessory		
AC Adapter	Brand Name	Avvio
	Model Name	SC050075-US
AC Adapter	Brand Name	Pulsare
	Model Name	SC050075-US
Battery	Brand Name	Avvio
	Model Name	G375061ARJ1
Battery	Brand Name	Pulsare
	Model Name	G375061ARJ1
Earphone	Signal Line Type	1.17m, non-shielded cable, without ferrite core
USB Cable	Signal Line Type	1.0m, shielded cable, without ferrite core

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 13 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607

Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 14 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 15 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01


Report No.: EP492607

Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 16 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 17 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607

Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 18 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607


Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 19 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607


Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 20 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01

Report No.: EP492607

Brand Name: Avvio, PULSARE Model Name: Avvio 786, Avvio 786S, Pulsare 786, Pulsare 786S



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: WVBA786X Page Number : 21 of 83
Report Issued Date : Nov. 24, 2014
Report Version : Rev. 01