
Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB240M Page Number : A1 of A3
Report Issued Date : Apr. 15, 2016
Report Version : Rev. 01


Report No.: FC631605

Report Template No.: BU5-FC15B Version 1.3

<Radiated Emission>

Mode 2

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB240M Page Number : A2 of A3
Report Issued Date : Apr. 15, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC631605

Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB240M Page Number : A3 of A3
Report Issued Date : Apr. 15, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC631605