
3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio PAD 10.1

Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 12 of 40
Report Issued Date : Jan. 02, 2014

Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 13 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 14 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 15 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01

Report No.: EP3D1001




TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 16 of 40
Report Issued Date : Jan. 02, 2014

Report Version : Rev. 01

Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 17 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 18 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 19 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 20 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01

Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 21 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01

Report No.: EP3D1001




TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 22 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01



Report No.: EP3D1001




TEL: 86-755-3320-2398 FCC ID: WVBA2000

Page Number : 23 of 40 Report Issued Date : Jan. 02, 2014 Report Version : Rev. 01



Report No.: EP3D1001




TEL: 86-755-3320-2398 FCC ID: WVBA2000

Page Number : 24 of 40 Report Issued Date : Jan. 02, 2014 Report Version : Rev. 01



Report No.: EP3D1001




TEL: 86-755-3320-2398 FCC ID: WVBA2000

Page Number : 25 of 40 Report Issued Date : Jan. 02, 2014 Report Version : Rev. 01




Report No.: EP3D1001




TEL: 86-755-3320-2398 FCC ID: WVBA2000

Page Number : 26 of 40 Report Issued Date : Jan. 02, 2014 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio PAD 10.1



TEL: 86-755- 3320-2398 FCC ID: WVBA2000 Page Number : 27 of 40
Report Issued Date : Jan. 02, 2014

Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 28 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 29 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 30 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 31 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 32 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 33 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01

Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 34 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 35 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 36 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01


Report No.: EP3D1001



TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 37 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: WVBA2000

Page Number : 38 of 40
Report Issued Date : Jan. 02, 2014
Report Version : Rev. 01



Report No.: EP3D1001




TEL: 86-755-3320-2398 FCC ID: WVBA2000

Page Number : 39 of 40 Report Issued Date : Jan. 02, 2014 Report Version : Rev. 01



Report No.: EP3D1001



TEL: 86-755-3320-2398 FCC ID: WVBA2000

Page Number : 40 of 40 Report Issued Date : Jan. 02, 2014 Report Version : Rev. 01