## 1. External Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 510 / Avvio 520

Report No.: EP410702




TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 1 of 24
Report Issued Date : Jan. 23, 2014



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 2 of 24
Report Issued Date : Jan. 23, 2014



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 3 of 24
Report Issued Date : Jan. 23, 2014

Report No.: EP410702



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 4 of 24
Report Issued Date : Jan. 23, 2014

Descriptions of the American Market Name of the American Food

**Report No.: EP410702** 



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 5 of 24 Report Issued Date : Jan. 23, 2014

Report No.: EP410702



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 6 of 24 Report Issued Date : Jan. 23, 2014

Brand Name: Avvio; Model Name: Avvio 510 / Avvio 520



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 7 of 24
Report Issued Date : Jan. 23, 2014

: Rev. 01

Report Version

Brand Name: Avvio; Model Name: Avvio 510 / Avvio 520



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 8 of 24
Report Issued Date : Jan. 23, 2014

## 2. Photograph of Accessory

Brand Name: Avvio; Model Name: Avvio 510 / Avvio 520

Report No.: EP410702

## **List of Accessory:**

Specification of Accessory		
AC Adapter	Brand Name	Avvio
	Model Name	DSA-3RNA-05 FUS 050065
Battery	Brand Name	Avvio
	Model Name	433450AR
USB Cable	Signal Line Type	1.0m, shielded cable, without core
Earphone	Signal Line Type	1.2m, unshielded cable, without core

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL : 86-755- 3320-2398 FCC ID : WVBA510X

Page Number : 9 of 24
Report Issued Date : Jan. 23, 2014

Report No.: EP410702



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 10 of 24
Report Issued Date : Jan. 23, 2014
Report Version : Rev. 01




TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 11 of 24
Report Issued Date : Jan. 23, 2014




Report No.: EP410702



TEL: 86-755-3320-2398 FCC ID: WVBA510X

Page Number : 12 of 24 Report Issued Date : Jan. 23, 2014 Report Version : Rev. 01



TEL: 86-755- 3320-2398 FCC ID: WVBA510X

Page Number : 13 of 24
Report Issued Date : Jan. 23, 2014
Report Version : Rev. 01