
1. External Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 776S, Avvio 776

Report No.: EP461309



TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 1 of 47
Report Issued Date : Jul. 10, 2014



Brand Name: Avvio; Model Name: Avvio 776S, Avvio 776



TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 2 of 47 Report Issued Date: Jul. 10, 2014

Brand Name: Avvio; Model Name: Avvio 776S, Avvio 776



TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 3 of 47
Report Issued Date : Jul. 10, 2014

Brand Name: Avvio; Model Name: Avvio 776S, Avvio 776



TEL: 86-755- 3320-2398 FCC ID: WVBA776X

Page Number : 4 of 47
Report Issued Date : Jul. 10, 2014



TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 5 of 47
Report Issued Date : Jul. 10, 2014





TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 6 of 47

Report Issued Date : Jul. 10, 2014 Report Version : Rev. 01

Photograph of Accessory 2.

Brand Name: Avvio; Model Name: Avvio 776S, Avvio 776

Report No.: EP461309

List of Accessory:


<u>=101 01 71000001 y1</u>		
Specification of Accessory		
AC Adapter	Brand Name	Avvio
	Model Name	A31-501000
Battery	Brand Name	Avvio
	Model Name	305452P
Earphone	Signal Line Type	1.2meter, non-shielded cable, without ferrite core
USB Cable	Signal Line Type	1meter, shielded cable, without ferrite core

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (SHENZHEN) INC. Page Number : 7 of 47 TEL: 86-755-3320-2398 Report Issued Date: Jul. 10, 2014

Report Version : Rev. 01 FCC ID: WVBA776X

Report No.: EP461309



TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 8 of 47

Report Issued Date : Jul. 10, 2014 Report Version : Rev. 01


Report No.: EP461309



TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 9 of 47
Report Issued Date : Jul. 10, 2014



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 10 of 47 Report Issued Date: Jul. 10, 2014



Report No.: EP461309



TEL: 86-755- 3320-2398 FCC ID: WVBA776X

Page Number : 11 of 47
Report Issued Date : Jul. 10, 2014

Report Version

: Rev. 01