
3. Internal Photograph of EUT


Brand Name: Avvio; Model Name: Avvio 402S /Avvio 402

Report No.: EP281601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 11 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 12 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 13 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 14 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 15 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 16 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01

Report No.: EP281601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 17 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01




Report No.: EP281601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402

: 18 of 26 Page Number Report Issued Date : Sep. 20, 2012 Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 19 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01





Report No.: EP281601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402

: 20 of 26 Page Number Report Issued Date : Sep. 20, 2012 Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 21 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01


Report No.: EP281601




Brand Name: Avvio; Model Name: Avvio 402S /Avvio 402

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 22 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 23 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01

Report No.: EP281601



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 24 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01

Report No.: EP281601



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 25 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA402 Page Number : 26 of 26
Report Issued Date : Sep. 20, 2012
Report Version : Rev. 01