
## 3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S

Report No.: EP282301



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : 29 of 62
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01



Report No.: EP282301




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 30 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Report No.: EP282301




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

: 31 of 62 Page Number Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Report No.: EP282301




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

: 32 of 62 Page Number Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 33 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S 8 8 80 9 2 , HILLIAND 80 90 20 80 12.04.12.N 2 60 9 40 30 20 10 100 90 80 70 60 50 40 30 20

0 80 10 60 50 40 30 20 10 100 80 80 70 60 50 40 30 20 80

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89


Page Number : 34 of 62 Report Issued Date : Oct. 11, 2012

Report No.: EP282301

Report Version : Rev. 01




Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

: 35 of 62 Page Number Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01


Report No.: EP282301



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : 36 of 62
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01



Report No.: EP282301



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 37 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Report No.: EP282301




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 38 of 62 Report Issued Date : Oct. 11, 2012 : Rev. 01 Report Version



Report No.: EP282301



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : 39 of 62
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : 40 of 62
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 41 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Report No.: EP282301




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 42 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Report No.: EP282301



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 43 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01

Report No.: EP282301




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : 44 of 62
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01



Report No.: EP282301



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 45 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 46 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Report No.: EP282301




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

: 47 of 62 Page Number Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Report No.: EP282301




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

: 48 of 62 Page Number Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 49 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 50 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01




Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 51 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01

Report No.: EP282301



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : 52 of 62
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S Sample 2 ngle SIM Card without Camera L30\_FMANT\_C\_VLO SYOS IS 9 08 30 Ob 20 e0 20 40 30 50 10 100 <del>8</del>0 80 <u>10</u> e0 20 40 30 50 *Q* 

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 53 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01

Report No.: EP282301



Report No.: EP282301




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 54 of 62 Report Issued Date : Oct. 11, 2012 : Rev. 01 Report Version



Report No.: EP282301




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 55 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 56 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 57 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 58 of 62 Report Issued Date : Oct. 11, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 289/289S/189/189S




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89

Page Number : 59 of 62 Report Issued Date : Oct. 11, 2012 : Rev. 01 Report Version



Report No.: EP282301



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : 60 of 62
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01


Report No.: EP282301



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : 61 of 62
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBAX89 Page Number : 62 of 62
Report Issued Date : Oct. 11, 2012
Report Version : Rev. 01