## 1. External Photograph of EUT

Brand Name: Avvio, PULSARE Model Name: Avvio 361S, Avvio 361, Pulsare 361S, Pulsare361

Report No.: EP4N2501



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 1 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501

Model Name: Avvio 361S, Avvio 361, Pulsare 361S, Pulsare361



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 2 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 3 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 4 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 5 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 6 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 7 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01


Report No.: EP4N2501



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 8 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 9 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 10 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 11 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501

Model Name: Avvio 361S, Avvio 361, Pulsare 361S, Pulsare361



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 12 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 13 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 14 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 15 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 16 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

## 2. Photograph of Accessory

Brand Name: Avvio, PULSARE

Report No.: EP4N2501

Model Name: Avvio 361S, Avvio 361, Pulsare 361S, Pulsare361

Specification of Accessory		
AC Adapter	Brand Name	Avvio
	Model Name	S050-050-US
AC Adapter	Brand Name	PULSARE
	Model Name	S050-050-US
Battery	Brand Name	Avvio
	Model Name	BL-4C
Battery	Brand Name	PULSARE
	Model Name	BL-4C
Earphone	Signal Line Type	100cm non-shielded without core
USB Cable	Signal Line Type	0.92m non-shielded without core

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 17 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 18 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01


Report No.: EP4N2501



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 19 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 20 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 21 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501

Model Name: Avvio 361S, Avvio 361, Pulsare 361S, Pulsare361



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 22 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 23 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501


Model Name: Avvio 361S, Avvio 361, Pulsare 361S, Pulsare361



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 24 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01

Report No.: EP4N2501

Model Name: Avvio 361S, Avvio 361, Pulsare 361S, Pulsare361



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA361X Page Number : 25 of 53
Report Issued Date : Jan. 13, 2015
Report Version : Rev. 01