## 3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 790S/790; Marketing Name: Avvio 790S/790

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 18 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 19 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 20 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 21 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 22 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 23 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 24 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 25 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 26 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 27 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 28 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 29 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 30 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 31 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 32 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 33 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 34 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 35 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01

Report No.: EP2O2302



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA790X Page Number : 36 of 36
Report Issued Date : Nov. 13, 2012
Report Version : Rev. 01