
# Appendix A. Setup Photographs

### <Conducted Emission>

### Mode 1



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ797X Page Number : A1 of A3
Report Issued Date : May 16, 2016
Report Version : Rev. 01

Report No. : FC640703


Report Template No.: BU5-FC15B Version 1.3

## CC Test Report No. : FC640703


### Mode 5

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ797X Page Number : A2 of A3
Report Issued Date : May 16, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


C Test Report No. : FC640703

### Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAQ797X Page Number : A3 of A3
Report Issued Date : May 16, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3