

# Appendix B. Setup Photographs

## <Conducted Emission>

Mode 3



Front View

#### Mode 4



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : B1 of B3
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01

Report No.: FC222801




## <Radiated Emission>

### Mode 3



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : B2 of B3
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01

Report No.: FC222801






Mode 4

LF





HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA560S Page Number : B3 of B3
Report Issued Date : Mar. 23, 2012
Report Version : Rev. 01

Report No.: FC222801