Appendix A. Setup Photographs

Mode 2



Mode 3



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA750X Page Number : A1 of A3
Report Issued Date : Sep. 28, 2014
Report Version : Rev. 01

Report No. : FC491201


<Radiated Emission>

Mode 2

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA750X Page Number : A2 of A3
Report Issued Date : Sep. 28, 2014
Report Version : Rev. 01

Report No. : FC491201




Mode 3

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA750X Page Number : A3 of A3
Report Issued Date : Sep. 28, 2014
Report Version : Rev. 01

Report No. : FC491201