

Report No.: FA2O0901

Appendix D. Product Photos



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAGT860 Page Number : D1 of D1
Report Issued Date : Oct. 16, 2012
Report Version : Rev. 01



Report No.: FA2O0901

Appendix E. Test Setup Photos





Front of the DUT with 1.5 cm Gap (Horizontal 0)

Back of the DUT with 1.5 cm Gap (Horizontal 0)





Back of the DUT with 1.5 cm Gap (Horizontal 180)

Back of the DUT with 1.5 cm Gap (Vertical 0)



Right Side of the DUT with 1.5 cm Gap (Horizontal 0)

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAGT860

Page Number : E1 of E1 Report Issued Date: Oct. 16, 2012 Report Version : Rev. 01