
3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 418S /Avvio 418


Report No.: EP2N1501



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S Page Number : 12 of 28
Report Issued Date : Nov. 29, 2012
Report Version : Rev. 01



Report No.: EP2N1501




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 13 of 28 Report Issued Date : Nov. 29, 2012 : Rev. 01 Report Version



Report No.: EP2N1501




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 14 of 28 Report Issued Date : Nov. 29, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 418S /Avvio 418




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 15 of 28 Report Issued Date : Nov. 29, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 418S /Avvio 418




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 16 of 28 Report Issued Date : Nov. 29, 2012 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 418S /Avvio 418




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 17 of 28 Report Issued Date : Nov. 29, 2012 Report Version : Rev. 01



Report No.: EP2N1501



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 18 of 28 Report Issued Date : Nov. 29, 2012 Report Version : Rev. 01

Report No.: EP2N1501



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S Page Number : 19 of 28
Report Issued Date : Nov. 29, 2012
Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 418S /Avvio 418 ple 2 for Sing **Bluetooth Antenna** 80 2 **WWAN** Antenna 8 20 80 40 30 20 Inn 20 0 40 30 20 20 40 OL 20 30 04 90 09 08 06 007 0 OT 08 08 001 OF 30 50

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 20 of 28 Report Issued Date : Nov. 29, 2012 Report Version : Rev. 01

Report No.: EP2N1501



Report No.: EP2N1501




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 21 of 28 Report Issued Date : Nov. 29, 2012 : Rev. 01 Report Version



Report No.: EP2N1501




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 22 of 28 Report Issued Date : Nov. 29, 2012 Report Version : Rev. 01



Report No.: EP2N1501




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 23 of 28 Report Issued Date : Nov. 29, 2012 : Rev. 01 Report Version



Brand Name: Avvio; Model Name: Avvio 418S /Avvio 418



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 24 of 28 Report Issued Date : Nov. 29, 2012 Report Version : Rev. 01


Report No.: EP2N1501



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S Page Number : 25 of 28
Report Issued Date : Nov. 29, 2012
Report Version : Rev. 01



Report No.: EP2N1501




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S

Page Number : 26 of 28 Report Issued Date : Nov. 29, 2012


Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S Page Number : 27 of 28
Report Issued Date : Nov. 29, 2012
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA418S Page Number : 28 of 28
Report Issued Date : Nov. 29, 2012
Report Version : Rev. 01