
## 3. Internal Photograph of EUT

Brand Name: Avvio / Model Name: Avvio 778S / Avvio 778

Report No.: EP411502



TEL: 86-755- 3320-2398 FCC ID: WVBA778X Page Number : 12 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01



Report No.: EP411502




TEL: 86-755-3320-2398 FCC ID: WVBA778X

Page Number : 13 of 39 Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01



Report No.: EP411502




TEL: 86-755-3320-2398 FCC ID: WVBA778X

: 14 of 39 Page Number Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 778S / Avvio 778




TEL: 86-755-3320-2398 FCC ID: WVBA778X

: 15 of 39 Page Number Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 778S / Avvio 778




TEL: 86-755-3320-2398 FCC ID: WVBA778X

: 16 of 39 Page Number Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: WVBA778X Page Number : 17 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 778S / Avvio 778


TEL : 86-755- 3320-2398 FCC ID : WVBA778X Page Number : 18 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 778S / Avvio 778

SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755- 3320-2398 FCC ID: WVBA778X Page Number : 19 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 778S / Avvio 778

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA778X Page Number : 20 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01



TEL : 86-755- 3320-2398 FCC ID : WVBA778X Page Number : 21 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01




Report No.: EP411502



TEL: 86-755-3320-2398 FCC ID: WVBA778X

Page Number : 22 of 39 Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01

Report No.: EP411502




TEL : 86-755- 3320-2398 FCC ID : WVBA778X Page Number : 23 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01



TEL : 86-755- 3320-2398 FCC ID : WVBA778X Page Number : 24 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01



**Report No.: EP411502** 



TEL: 86-755-3320-2398 FCC ID: WVBA778X

Page Number : 25 of 39 Report Issued Date : Feb. 12, 2014 : Rev. 01 Report Version



Report No.: EP411502




TEL: 86-755-3320-2398 FCC ID: WVBA778X

Page Number : 26 of 39 Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 778S / Avvio 778




TEL: 86-755-3320-2398 FCC ID: WVBA778X

Page Number : 27 of 39 Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 778S / Avvio 778




TEL: 86-755-3320-2398 FCC ID: WVBA778X

: 28 of 39 Page Number Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio 778S / Avvio 778




TEL: 86-755-3320-2398 FCC ID: WVBA778X

Page Number : 29 of 39 Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01




TEL: 86-755- 3320-2398 FCC ID: WVBA778X Page Number : 30 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01




Brand Name: Avvio / Model Name: Avvio 778S / Avvio 778


SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA778X Page Number : 31 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01





TEL : 86-755- 3320-2398 FCC ID : WVBA778X Page Number : 32 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01





SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA778X Page Number : 33 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01



Report No.: EP411502



TEL: 86-755-3320-2398 FCC ID: WVBA778X


Page Number : 34 of 39 Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: WVBA778X

Page Number : 35 of 39 Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01


Report No.: EP411502



TEL : 86-755- 3320-2398 FCC ID : WVBA778X Page Number : 36 of 39
Report Issued Date : Feb. 12, 2014
Report Version : Rev. 01



Report No.: EP411502




TEL: 86-755-3320-2398 FCC ID: WVBA778X

Page Number : 37 of 39 Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01



Report No.: EP411502




TEL: 86-755-3320-2398 FCC ID: WVBA778X

Page Number : 38 of 39 Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01



Report No.: EP411502



TEL: 86-755-3320-2398 FCC ID: WVBA778X

Page Number : 39 of 39 Report Issued Date : Feb. 12, 2014 Report Version : Rev. 01