

Report No.: FA260403

Appendix D. Product Photos






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA921 Page Number : D1 of D2
Report Issued Date : Jul. 05, 2012
Report Version : Rev. 01



Report No.: FA260403

Antenna Location:



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA921 Page Number : D2 of D2
Report Issued Date : Jul. 05, 2012
Report Version : Rev. 01



Report No. : FA260403

Appendix E. Test Setup Photos





Right Cheek









Left Tilted



Front of the DUT with Phantom 1.5 cm Gap



Back of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA921 Page Number : E1 of E1
Report Issued Date : Jul. 05, 2012
Report Version : Rev. 01