


Report No.: FR590902B

<Conducted Emission>

Appendix B. Setup Photographs



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB135M


Page Number : B1 of B2 Report Issued Date: Oct. 14, 2015 Report Version : Rev. 01




Report No.: FR590902B

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB135M Page Number : B2 of B2
Report Issued Date : Oct. 14, 2015
Report Version : Rev. 01