


Appendix A. Setup Photographs

<Radiated Emission>


For 22H

Y Plane

LF



HF



SPORTON INTERNATIOINAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA750X Page Number : A1 of A2
Report Issued Date : Sep. 28, 2014
Report Version : Rev. 01

Report No. : FG491201







For 24E

Y Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA750X

Page Number : A2 of A2 Report Issued Date : Sep. 28, 2014 Report Version : Rev. 01

Report No. : FG491201