


Report No. : FA381603

Appendix D. Test Setup Photos





Right Cheek

Right Tilted





Left Cheek

Left Tilted

SPORTON INTERNATIONA (XI'AN) INC.

TEL: 86-029-8860-8767 FCC ID: WVBA765X Page Number : D1 of D2
Report Issued Date : Sep. 13, 2013
Report Version : Rev. 02





Front of the DUT with Phantom 1cm Gap



Report No. : FA381603


Back of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONA (XI'AN) INC.

TEL: 86-029-8860-8767 FCC ID: WVBA765X

Page Number : D2 of D2 Report Issued Date : Sep. 13, 2013 Report Version : Rev. 02